

SERVICE BULLETIN

SUBJECT:

Flap drive check of the Legend 540 (Legend 600) after 500 hours

AFFECTED PRODUCTS:

Legend 540 and Legend 600

COMPLIANCE:

MANDATORY

INSTRUCTIONS:

After 500 hours of flight, disconnect the actuator from the push bowden in the centroplan.
Disconnect the flaps at the other end. Try bowden freedom of movement. If bowden is not loose or it is blocked, replace bowden or contact your dealer or manufacturer directly (Aeropilot s.r.o.).