



AEROPILOT Ltd.

LEGEND

RELEASE DATE: 15.11.2018

EFFECTIVE DATE: 15.11.2018

NOTICE ID: 1801

SERVICE BULLETIN NO. 1801

SUBJECT:

Flap drive check in the Legend 540 (Legend 600) aircraft after 500 flight hours

AFFECTED PRODUCTS:

Legend 540 and Legend 600

COMPLIANCE:

Mandatory

INSTRUCTIONS:

After 500 hours of flight, disconnect the actuator from the push bowden in the centre plane. Disconnect the flaps at the other end. Try bowden freedom of movement. If bowden is not loose or it is blocked, replace bowden or contact your dealer or manufacturer Aeropilot s.r.o. directly.