

## **SERVICE BULLETIN**

**SUBJECT:**

Divided aircraft ceilings

**AFFECTED PRODUCTS:**

Legend 540 and Legend 600

**COMPLIANCE:**

MANDATORY

**INSTRUCTIONS:**

For older aircraft ceilings, the ceiling was screwed from three parts. If you have this design please check if the tensioner screw of transverse steering cannot capture for the connection of ceilings. In case of doubts, take a photo documentation and contact us for a consultation.