



**AEROPILOT Ltd.**

**LEGEND**

RELEASE DATE: 07.01.2019

EFFECTIVE DATE: 07.01.2019

NOTICE ID: 1902

## **SERVICE BULLETIN NO. 1902**

### **SUBJECT:**

Divided aircraft ceiling

### **AFFECTED PRODUCTS:**

Legend 540 and Legend 600

### **COMPLIANCE:**

Mandatory

### **INSTRUCTIONS:**

For older aircraft ceilings, the ceiling was screwed of three parts. If you have such design, please check if the tensioner screw of transverse steering cannot capture the connections of the ceiling. In case of doubts, take photo documentation and contact us for a consultation.