



**AEROPILOT Ltd.**

**LEGEND**

RELEASE DATE: 27.03.2019

EFFECTIVE DATE: 27.03.2019

NOTICE ID: 1903

## **SERVICE BULLETIN NO. 1903**

### **SUBJECT:**

Autopilot

### **AFFECTED PRODUCTS:**

Legend 540 and Legend 600

### **COMPLIANCE:**

Mandatory

### **INSTRUCTIONS:**

We warn pilots using autopilot about the possibility of electronics failure. For security reasons, it is necessary to turn on the switch “autopilot servo” at a minimum height of 1000 ft AGL. In case of any autopilot malfunction, turn off the autopilot with the red button on the left yoke and take control.