



AEROPILOT Ltd.

LEGEND

RELEASE DATE: 09.06.2023

EFFECTIVE DATE: 09.06.2023

NOTICE ID: 2306

SERVICE BULLETIN

SUBJECT:

Plastic throttle replacement

AFFECTED PRODUCT:

Legend 600 serial numbers: 2076, 2077, 2080, 2082, 2181, 2183, 2184, 2185, 2186, 2187, 2189, 2190, 2191, 2192, 2193, 2295, 2299, 22100, 22101, 22104, 22105

COMPLIANCE:

MANDATORY

INSTRUCTIONS:

For all Legend 600 aircrafts that are equipped with a plastic throttle, we issue a ban on aircraft operations until the throttle is replaced.



AEROPILOT Ltd.
1815 Jeníkovská
28601 Čáslav
Czech Republic

Tel.: +420 605 296 563
E-mail: info@aeropilotcz.com
www.aeropilotcz.com
VAT: CZ27108431