

SERVICE BULLETIN

SUBJECT:

Autopilot

AFFECTED PRODUCTS:

Legend 540 and Legend 600

COMPLIANCE:

MANDATORY

INSTRUCTIONS:

We warn the pilots using an autopilot about a possibility of electronics failure. For the safety reasons it is necessary to turn on a switch „servo autopilot“ at a minimum height 1 000 AGL. In case of any autopilot disorder turn off an autopilot by a red button on the left yoke and take the control.