



AEROPILOT Ltd.

LEGEND

RELEASE DATE: 24.05.2019

EFFECTIVE DATE: 24.05.2019

NOTICE ID: 1905

SERVICE BULLETIN NO. 1905

SUBJECT:

Switching fuel tanks in a fuel system without a collection center hull fuel tank

AFFECTED PRODUCT:

Legend aircraft without a collection center hull fuel tank

COMPLIANCE:

Mandatory

INSTRUCTIONS:

During flight with minimum fuel level, do not switch the fuel valve to the position "BOTH". When it slips or slides, there is a risk of fuel spilling into one of the wing fuel tanks and the pump sucks in air and the engine stops temporarily. If this happens, switch immediately to the fuel tank where you have fuel and turn on the backup pump.