



RELEASE DATE: 09.06.2023

EFFECTIVE DATE: 09.06.2023

NOTICE ID: 2307

## **SERVICE BULLETIN NO. 2307**

### **SUBJECT:**

Replacing the plastic throttle

### **AFFECTED PRODUCTS:**

Legend 600 aircraft serial numbers: 2076, 2077, 2080, 2082, 2181, 2183, 2184, 2185, 2186, 2187, 2189, 2190, 2191, 2192, 2193, 2295, 2299, 22100, 22101, 22104, 22105

### **COMPLIANCE:**

Mandatory

### **INSTRUCTIONS:**

For all Legend 600 aircraft that are equipped with a plastic throttle, we are issuing a ban on aircraft operations until the throttle is replaced.

