



RELEASE DATE: 28.01.2025

EFFECTIVE DATE: 28.01.2025

NOTICE ID: 2509

SERVICE BULLETIN NO. 2509

SUBJECT:

Correct use of heating

AFFECTED PRODUCT:

Legend 600 / L600

COMPLIANCE:

Advisory

INSTRUCTIONS:

1. At air temperatures below 20°C, cover the oil cooler with filter foam (if you don't have it, we can send it to you).
2. The heating exchanger flap must be closed.
3. The heating flaps are open when needed.

